

VEHICLE INSPECTION REPORT

NGET34311

KUBOTA B2110

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date		Colour		Axle Combi	4WD
Year	2006	VIN	30966	Rear Suspension	Steel
Mileage	416 Hours Warranted	Body Style	TRACTOR		
Fuel Type	DIESEL	Gearbox	HYDROSTATIC		

OIL LEAK 4FT 6" PLOUGH BLADE, VICON PTO DRIVEN SPREADER

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Steering	OK
Windows	OK		